

Marvel-Schebler Carbureter Division, Borg-Warner Corporation, Flint, Michigan, U. S. A.

Marvel-Schebler No.	Customer No.	Size	Customer	Model	Year
TSX-181	KS-393	1"	Oliver	88HC	1948
Replace with TSX-374	KS-393B				

Row Crop to #121300 Standard to #820485 Industrial to #920265

Marvel Part No.	Oliver Part No.	Part Name
10-3068	KS-393	Carbureter Assembly Complete
10-3167	KS-7601	Carbureter Body Assembly
13-916	KS-7606	Throttle Shaft Assembly
14-225	K-7634	Valve—Throttle (15°)
15-42	H-7646	Screw (#8-32 x 3/4" Fill. Head) Throttle Adjusting
15-285	H-7640	Screw (#8-32 x 5/16" Fill. Head) Choke Swivel—1; Choke Bracket Clip—1
15-483	C-7643-A	Screw (#6-32 x 1/4" "Sems" Binding Head) Choke Valve—2; Throttle Valve—2
15-A85	K-7645	Screw (#12-24 x 3/4" "Sems" Fill. Head) Throttle Body to Bowl
15-A93	K-7644	Screw (#8-32 x 3/8" "Sems" Fill. Head) Choke Bracket.....
16-4	H-7653	Gasket—Float Valve Seat
16-47	K-7668	Power Adjusting Needle Seat and Bowl Plug.....
16-456	F-7654	Gasket—Nozzle (Schebler P-894)
16-A41	K-7655	Gasket—Throttle Body to Bowl
16-654	KS-7655	Gasket Assortment
24-262	H-7617	Spring—Throttle Stop Screw
24-340	H-7658	Spring—Idle Needle
24-A3	A-7630	Spring—Choke Return
26-666	KS-7631	Choke Shaft Assembly
27-540	KS-7635	Choke Valve Assembly.....
28-49	H-7620	Swivel—Choke
29-538	KS-7609	Choke Bracket Assembly
30-631	KS-7605	Float and Lever Assembly
32-16	F-7626	Shaft—Float
36-295	K-7615	Power Adjusting Needle Seat and Bowl Plug
43-33	H-7628	Needle—Idle Adjusting
43-624	KS-7614	Power Adj. Needle, Seat, Packing and Packing Retainer Assy....
44-27	F-7611	Packing—Throttle Shaft
44-38	H-7666	Packing—Choke Shaft
44-51	K-7636	Packing—Power Adjusting Needle
46-A10	K-7635	Venturi (3/4" Diameter Throat)
47-318	K-7629	Main Nozzle
49-101-L	H-7613	Jet—Idle
55-261	K-7641	Retainer—Throttle Shaft Packing
55-285	K-7637	Retainer—Power Adjusting Needle Packing
80-171	Plug—Idle Drilling
82-16	H-7619	Cotter—Choke Swivel
99-7	H-7639	Drain Plug
227-1129	KS-7600	Throttle Body Assembly
233-543	FS-7623	Float Valve, Seat and Gasket Assembly (Matched)
286-843	Repair Kit

Parts included in repair kit are shown in bold type

Float Setting: 1/4" from the gasket to the nearest surface of the float.

IN SERVICE REPLACE COMPLETE CARBURETER WITH TSX-374