

Marvel-Schebler Carbureter Division, Borg-Warner Corporation, Flint, Michigan, U. S. A.

| | | | | | |
|---------------------|--------------|--------|----------|-------|------|
| Marvel-Schebler No. | Customer No. | Size | Customer | Model | Year |
| TTX-19 | CS-393C | 1 1/4" | Oliver | 80 HC | 1938 |

Row Crop #109152 Standard #803929 Industrial #900315

| Symbol No. | Marvel Part No. | Oliver Part No. | Part Name |
|------------|-----------------|------------------|---|
| | TTX-19 | CS-393-C | Carbureter Assembly Complete |
| 3 | X-2931 | AS-7600 | Carbureter Body (Upper Half) |
| 4 | X-2923 | CS-7601-A | Carbureter Body (Lower Half) |
| 6 | P-1036 | C-7655 | Gasket—Bowl |
| 8 | S-750A | C-7649 | Lock Washer—Body Screw (5) |
| 8 | S-1393A | | Lock Washer—Float Shaft |
| 23 | S-2300A | C-7640 | Strainer Nut |
| 24 | P-710 | C-7657 | Gasket—Strainer Nut |
| 25 | X-2560 | CS-7619 | Strainer Assembly |
| 25 | S-2570 | C-7664 | Strainer—Fuel Drain |
| 26A | S-2289 | C-7639 | Drain Valve |
| 27 | X-2921 | CS-7606-A | Throttle Shaft and Lever Assembly |
| 28 | 60-261 | A-7602 | Bushing—Throttle Shaft (2) |
| 29 | S-211F | C-7633 | Choke Lever Stop Pin |
| 30 | P-1041 | C-7634 | Throttle Valve (21°) |
| 31 | 15-483 | C-7643-A | Screw—Throttle Valve (2) |
| 52 | S-2587 | C-7636 | Seat—Power Adjusting Needle |
| 57 | T30-P | C-7638-A | Venturi (1 3/8" Diameter Throat) |
| 58 | S-2568 | C-7629 | Nozzle |
| 59 | P-894 | | Gasket—Nozzle |
| 60 | X-2554 | CS-7604 | Float and Lever Assembly |
| 61 | S-2170 | C-7650 | Float Lever Shaft |
| 61 | X-2404A | CS-7626 | Float Lever Shaft, Nut and Washer Assembly |
| 65 | P-228 | C-7648 | Nut—Float Lever Shaft |
| 66 | P-541 | C-7653 | Gasket—Float Valve Seat (2) |
| 85 | S-2491 | C-7613 | Idle Tube |
| 92 | SK-46 | C-7646 | Adjusting Screw—Throttle Stop |
| 96 | SK-42 | C-7645 | Body Screw (#10-24 x 3/4") |
| 96 | SK-45 | C-7647 | Body Screw (#10-24 x 1 1/8") |
| 96 | SK-46 | C-7646 | Body Screw (#10-24 x 7/8") (3) |
| 121 | X-2897 | CS-7631 | Choke Shaft and Lever Assembly |
| 131 | S-2056 | C-7637 | Connection—Power Adjusting Needle |
| 137 | P-1040 | C-7635 | Choke Valve (15°) |
| 150 | 51-B | C-7658 | Spring—Idle Adjusting Needle |
| 150 | 51-S | C-7659 | Spring—Throttle Stop Adjusting Screw |
| 165 | X-2765 | CS-7628 | Idle Adjusting Needle |
| 166 | X-2903 | CS-7614 | Power Adjusting Needle Assembly |
| 171 | P-1202 | C-7665 | Expansion Plug—Strainer Retaining |
| 186 | 15-483 | C-7643-A | Screw—Choke Valve (2) |
| 187 | 51-EE | C-7630 | Spring—Choke Return |
| 191 | S-2082A | C-7642 | Lock Screw—Venturi |
| 194 | S-763 | C-7612 | Drill Plug—Back Suction Channel |
| 194 | S-2041 | C-7651 | Drill Plug (1/4"-28) |
| 194 | S-2083 | C-7652 | Drill Plug (5/16"-24) (2) |
| 194 | S-2456 | C-7661 | Drill Plug—Idle Channel |
| 195 | S-2073A | C-7609 | Lead Ball (7/32" Diameter Bowl Bleed) |
| 195 | S-2073B | C-7610 | Lead Ball—Nozzle |
| 197 | P-556 | C-7611 | Expansion Plug—Choke Shaft |
| 197 | P-1219 | A-7641 | Expansion Plug—Throttle Shaft Cup |
| 200 | S-2563 | C-7660 | Plug—Economizer Restriction |
| 207 | P-1025A | C-7625 | Float Lever Bracket |
| 225 | P-1218 | A-7667 | Retainer—Throttle Shaft Packing |
| 265 | S-2599 | C-7666 | Packing—Throttle Shaft |
| 289 | P-791 | C-7656 | Gasket—Power Adjusting Needle Connection |
| 332 | X-2840 | CS-7623 | Float Valve and Seat Assembly (Matched) |
| 350 | 16-622 | | Gasket Assortment |
| 355 | 286-556 | | Repair Kit |

Parts included in repair kit are shown in bold type

Float Setting: 2" from the face of the flange to the bottom of the float.