

Marvel-Schebler Carbureter Division, Borg-Warner Corporation, Flint, Michigan, U. S. A.

| | | | | | |
|----------------------------|---------------------|---------------|----------------------------|--------------|-------------|
| Marvel-Schebler No. | Customer No. | Size | Customer | Model | Year |
| DLTX-63 | A2544R | 1 1/2" | John Deere—Waterloo | D | 1947 |
| Replaces DLTX-6 | AD830R | | | | |
| Replaces DLTX-16 | AD830R | | | | |

Tractor Serial No. 161645 -

| Symbol No. | Part No. | Part Name | Symbol No. | Part No. | Part Name |
|-------------------|-----------------|---|-------------------|-----------------|--|
| | DLTX-63 | Carbureter Assembly Complete..... | 97 | S-2154 | Screw—Choke Lever Friction Spring..... |
| 2 | 10-2534 | Body and Bushings Assembly..... | | | |
| 5 | DLT-13 | Bowl Casting | 101 | S-2192 | Connection—Fuel |
| 6 | P-951 | Gasket—Bowl | 121 | 26-626 | Choke Shaft & Lever Assembly..... |
| 6 | P-710 | Gasket—Bowl Retaining Nut..... | 137 | P-348 | Choke Valve |
| 7 | S-2424 | Nut—Bowl Retaining | 144 | P-52 | Washer—Choke Friction Spring..... |
| 8 | P-850 | Washer—Choke Friction Spring.... | 144 | S-245 | Lock Washer—Throttle Valve Screw..... |
| 8 | S-1393 | Lock Washer—Choke Valve Screw | | | |
| 24 | P-950 | Gasket—Strainer Assembly | 162 | S-251A | Ball (Friction)—Adjusting Needle |
| 25 | X-2462 | Fuel Inlet Strainer Assembly..... | 165 | X-2461 #3 | Needle—Idle Adjusting |
| 26 | 87-3A | Drain Cock | 166 | X-2548 #1 | Needle—Load Adjusting |
| 27 | S-2369 | Throttle Shaft | 173 | 25-J | Spring—Nozzle Retaining |
| 28 | S-2471 | Bushing—Throttle Shaft (Upper) | 174 | 1-K | Spring—Friction Adj. Needle..... |
| 28 | S-2482 | Bushing—Throttle Shaft (Lower) | 174 | 25-V | Spring (Friction)—Choke Lever.. |
| 30 | P-948 | Throttle Valve | 186 | 15-29 | Screw—Choke Valve |
| 31 | 15-285 | Screw—Throttle Valve | 187 | 18-0 | Spring—Throttle Lever Stop Pin.. |
| 32 | X-2754 | Throttle Shaft and Lever Assembly | 194 | 15-392 | Drill Plug |
| 58 | 47-649 | Nozzle | 194 | S-1506 | Drill Plug (3/32"-32)..... |
| 60 | 30-635 | Float and Lever Assembly..... | 194 | S-2041 | Drill Plug (1/4"-28)..... |
| 61 | S-2146 | Pin—Float Lever Pivot..... | 194 | S-2502 | Drill Plug (#10-32)..... |
| 62 | S-2147 | Bearing—Float Lever Pivot Pin... | 195 | S-98 | Pipe Plug (Hex. Head)..... |
| 66 | 16-364 | Gasket—Float Valve Seat..... | 195 | S-98B | Pipe Plug (Headless)..... |
| 92 | 15-57 | Screw—Throttle Lever Adjusting.. | 195 | S-2151E | Economizer Plug |
| 97 | 15-469 | Screw (Clamp)—Throttle Lever Adjusting..... | 234 | S-211G | Pin—Throttle Lever Stop..... |
| | | | 332 | X-2653 | Matched Float Valve, Seat and Gasket Assembly..... |
| | | | | | |
| | | | | 16-663 | Gasket Assortment |
| | | | | 286-873 | Repair Kit |

Replaces DLTX-6 and DLTX-16 in Service

REFER TO SERVICE PARTS PLATE ON PAGE 28