

Marvel-Schebler Carbureter Division, Borg-Warner Corporation, Flint, Michigan, U. S. A.

Marvel-Schebler No.	Customer No.	Size	Customer	Model	Year
TTX-16	GE-6B	1 1/4"	Minneapolis-Moline	GT Tractor GU-GUA Unit	1937-38

GE Engine No. 901058 to 903272

Symbol No.	Marvel Part No.	Minneapolis-Moline Part No.	Part Name
	TTX-16	GE-6B	Carbureter Assembly Complete
3	X-2796	FE-6345	Carbureter Body (Upper Half).....
4	X-2797	KE-7289	Carbureter Body (Lower Half).....
6	P-1036	KE-7203	Gasket—Bowl
8	S-1393A	KE-7291	Lock Washer—Float Lever Shaft Nut (1).....
8	S-750A	KE-7292	Lock Washer—Body Screw (5).....
23	S-2300A	KE-7207	Strainer Nut
24	P-710	KE-7208	Gasket—Strainer Nut
25	X-2560	KE-7209	Strainer Assembly
25	S-2570	Strainer—Fuel Drain
26A	S-2289	KE-7210	Drain Valve
27	S-2290	KE-7211	Throttle Shaft
28	60-261	KE-7294	Bushing—Throttle Shaft (2).....
30	P-1041	FE-6347-A	Throttle Valve (21°)
31	15-483	LE-7019	Screw—Throttle Valve (2).....
32	X-2957	Lever—Throttle Stop
32	X-2563	KE-7215	Throttle Lever Assembly—Governor
41	X-2954	Choke Shaft Lever
52	S-2494	FE-6348	Seat—Fuel Adjusting Needle
57	T-30K	FE-6349	Venturi (1 1/16" Diameter Throat).....
58	S-2488	FE-6350	Nozzle
59	P-894	KE-7218	Gasket—Nozzle
60	X-2554	KE-7219	Float and Lever Assembly.....
61	S-2170	Float Lever Shaft
61	X-2404A	KE-7220	Float Lever Shaft, Nut and Washer Assembly.....
65	P-228	Nut—Float Lever Shaft
66	P-541	KE-7223	Gasket—Float Valve Seat (2).....
85	S-2491	FE-6351	Idle Tube
92	SK-46	KE-7311	Adjusting Screw—Throttle Stop
93	SJ-15	KE-7239	Clamp Screw—Choke Lever
93	SL-18	KE-7239	Clamp Screw—Governor Lever
93	S-93B	KE-7299	Retainer Screw—Throttle Stop Lever
96	SK-42	KE-7225	Body Screw (#10-24 x 3/4")
96	SK-45	KE-7227	Body Screw (#10-24 x 1 1/8")
96	SK-46	KE-7311	Body Screw (#10-24 x 7/8") (3).....
121	S-2291	KE-7231	Choke Shaft
131	S-2056	KE-7232	Connection—Fuel Adjusting Needle
137	P-1040	KE-7233	Choke Valve (15°).....
150	51-B	KE-7234	Spring—Idle Adjusting Needle
150	51-S	KE-7241	Spring—Throttle Stop Adjusting Screw.....
165	X-2765	KE-7300	Idle Adjusting Needle
166	X-2798	KE-7301	Fuel Adjusting Needle Assembly.....
171	P-1202	KE-7313	Expansion Plug—Strainer Retainer.....
186	15-483	LE-7019	Screw—Choke Valve (2).....
191	S-2082A	KE-7243	Lock Screw—Venturi
194	S-763	Drill Plug (#8-32) Back Suction Channel.....
194	S-2041	KE-7245	Drill Plug (1/4"-28).....
194	S-2083	KE-7246	Drill Plug (5/16"-24) (2).....
194	S-2456	KE-7302	Drill Plug—Idle Channel
195	S-2073A	KE-7247	Lead Ball (3/32" Diameter) Bowl Bleed (2).....
195	S-2073B	KE-7248	Lead Ball—Nozzle
197	P-556	KE-7249	Welch Plug—Choke Shaft
197	P-881	KE-7304	Welch Plug—Throttle Shaft
200	S-2500	FE-6352	Plug—Economizer Restriction
207	P-1025A	KE-7252	Float Lever Bracket
289	16-29	Gasket—Fuel Adjusting Needle
289	P-791	KE-7254	Gasket—Fuel Adjusting Needle Connection
332	X-2840	KE-7306	Float Valve and Seat Assembly (Matched).....
347	S-2293	KE-7234	Plunger—Choke Friction
348	51-L	KE-7240	Plunger Spring
	16-622	Gasket Assortment
	286-552	Repair Kit

Parts included in Repair Kit are shown in bold type

Float setting: 2" from the face of the flange to the bottom of the float.